CERTIFICATE

It is certified that building Nos Block A, Block B, Block C and staff quarters are verified visually and found no superficial structural defects in the Kendriya Vidyalaya No-2, Jalandhar Cantt.

Çantt ation : Date

(Gaurav Tripathi) Capt AGE B/R-1 (West) JRC

CERTIFICATE

12

It is certified that building Nos Block A, Block B, Block C and staff quarters are verified visually and found no superficial structural defects in the Kendriya Vidyalaya No-2, Jalandhar Cantt.

Jalandhaf Santt Station : Dated

(Gaurav Tripathi) Capt AGE B/R-1 (West) JRC

केन्द्रीय लिल्पलय नं 2 Kendriya Vidyalaya No. 2 जालन्धर हावनी/Julandhar Gan'